

APPENDIX F

BRIDGE MAINTENANCE SCHEMES PROGRAMME 2010/2011

BRIDGE No	ROAD No	LOCATION	DESCRIPTION	COST BAND	NOTES
288	A6003	Rockingham Road Flood span 1	Waterproof deck, concrete repairs, replace parapet fence.	C	On Site
290	A6003	Rockingham Road Flood span 3	Waterproof deck, concrete repairs, replace parapet fence.	C	On Site
291	A6003	Rockingham Road Flood span 4	Waterproof deck, concrete repairs, replace parapet fence.	C	On Site
292	A6003	Rockingham Road Flood span 5	Waterproof deck, concrete repairs, replace parapet fence.	C	On Site
382	A4304	River Swift Lutterworth Southern Bypass	Replace bridge joints	C	Design being prepared
465	B664	Stockerstone Bridge	Scour protection and brickwork repairs	C	Design being prepared
493	C9411	Farndon Road Mkt. Harborough	Brickwork repairs	C	Design being prepared
805	C8404	Medbourne Road, Upper Leighs Farm	Bridge demolition and infill	C	Design being prepared
1008		Glen Road, Burton Overy	Brickwork repairs	C	Design being prepared
1127		Wistow Road, Wistow	Brickwork repairs	C	Design being prepared
634	C4502	Near Wistow Grange	Waterproofing and brickwork repairs	C	Design being prepared

Key:- C < £50k;
 B £50k - £150k;
 A > £150k