



1 General View of Roof at East Elevation



2. General View of Roof at West Elevation



3. Detail View of Roof Slate



4. General View of Roof at West Elevation





5. General View of PVCu guttering/snow guard – East Elevation



6. General View of PVCu guttering/snow guard – East Elevation



7. General View of Cast Iron gutter/snow guard – East Elevation



8. General View of Cast Iron gutter/snow guard – East Elevation





9. General View of Gable-End - North Elevation



10. Detail View of Undercloak Verge - North Elevation



11. General View of Strip Glazing



12. Detail View of Bottom edge Strip Glazing



13. General View of inside Glazing Units



14. Detail View of Top edge of Glazing Unit



15. Detail View of inside bottom Glazing Unit



16. Detail View of inside bottom Glazing Unit





17. General View of Dormer – East Elevation



18. General View of Dormer – East Elevation



19. General View of Pitched-Hipped Roof – North Elevation



20. General View of Pitched-Hipped Roof – North Elevation





21. View of Rainwater Pipe to replace – Abutment of Rear Wing/Main Building



22. General View of neighbouring properties – West Elevation



23. General View of neighbouring properties – West Elevation



24. General View of neighbouring properties – West Elevation